



Solid Surface Baths

CARE AND MAINTENANCE

When receiving your Bath, the unit will be covered with protective packaging materials for transport purposes. Remove all the packaging material covering the bath, checking carefully for any damages. We will not accept any claims for damages or inaccuracies 48 hours after receipt of goods or installation.

HIGH GLOSS FINISH

- To preserve the polished surface, clean your bath with a soft cloth and warm soapy water.
- As a weekly cleaner we recommend any suitable sanitary ware liquid cleaner. Rinse the surface clean immediately afterwards. Do not allow any liquid cleaner to stand for extended periods as this may stain the bath depending on the type of cleaning product.
- Do not use powders, pastes, crème cleaners, thinners or dry cleaning fluids.
- Stubborn marks and fine scratches may be removed using 1500-2000 grit water paper. Follow this by polishing with a car burnishing compound and soft cloth.
- Should you need to disinfect your bath, a weak bleach solution may be left to soak for 20-30 minutes.

EURO SILK MATT FINISH

- Clean your bath with a soft cloth and warm soapy water.
- As a weekly cleaner we recommend any suitable sanitary ware liquid cleaner. Rinse the surface clean immediately afterwards. Do not allow any liquid cleaner to stand for extended periods as this may stain the bath depending on the type of cleaning product.
- Stubborn marks and fine scratches may be removed with the Scotchbrite pad provided with your bath.
- Should you need to disinfect your bath, a weak bleach solution may be left to soak for 20-30 minutes.

DAMAGE PREVENTION

- Always run hot and cold water simultaneously into your bath or vanity. Geyser settings should not exceed a maximum temperature of 60°C.
- Deliver water (mixed hot and cold) to the lowest point of the bath which is at the waste area
- Avoid contact with strong chemicals and solvents (stain removers, nail varnish removers, Etc)
- Wipe away any chemical spillages ie. hairdye, as soon as possible to avoid potential staining.
- When coloured essential oils are used, first test that the colour will not stain your bath. If it does, a burnishing compound will remove it.